



Upstream  
East Gate  
March 2001



Atmospheric  
area has rust  
stains bleeding  
from joints.



Zebra mussels on lower portion of gate  
may hide corrosion.



Coating on bottom flange of gates  
is commonly damaged.